



VOLVO V40: 1ERW877			
Vinnnumber:	YV1MV8481D2045730	Versionname:	V40 D2 Base 115PK
First Registrationdate:	5/03/2013	Fiscalpower:	
Expertise Mileage:	106020	Power Kw:	84
Bodytype:	Hatchback	Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4121
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	205/55/16/91 T LightMetal			
	Fr.L.	Uniroyal: 7 mm	Fr.R.	Uniroyal: 7 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			2231,00
Front bumper, Scratch(es), LI - Repair and paint (complete)			211,80



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	---------------

  			Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
 			Interior, Stain, Cleaning	50,00
  				
  				
				
			Alloy rim R R, Scratch(es), Acceptable	0,00
			No pictures to display	
			Windscreen, Stone chip(s), Acceptable	0,00
			No pictures to display	
			Roof, Scratch(es), 67 - Polish	55,19
 				
			Alloy rim F R, Scratch(es), E - Replace	235,20
  				
			Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
 				
			Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	0,00
  				
			Alloy rim F L, Deformed, E - Replace	235,20
  				
			Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18



Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R R, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Panoramic roof, Scratch(es), E - Replace	0,00
--	------

