



VOLVO V40: 1FAM158			
Vinnnumber:	YV1MV8481D2058901	Versionname:	V40 D2 Base 115PK
First Registrationdate:	7/05/2013	Fiscalpower:	
Expertise Mileage:	184517	Power Kw:	84
Bodytype:		Body color:	White
Gearbox:	MAN 6 VIT	Paint type:	Opaque
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3116
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 3,5 mm	Fr.R.	Michelin: 3,5 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1215,12
Rearview mirror L complete, Damaged, E - Replace			168,00



Grill frame, Missing, E - Replace	15,00
-----------------------------------	--------------





Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Rocker panel inner R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Door panel F L, Deformed, Repair/replace (lump sum) 49,00



Alloy rim R R, Damaged, E - Replace 235,20



Wing R R, Bump(s), PDR - Knock out without painting 135,00



Rocker panel inner F L, Scratch(es), LI - Repair and paint (complete) 115,56

