


LU Skoda Superb Combi: VU8883

Vinnnumber:	TMBLJ9NP2G7078740	Versionname:	2.0 TDI CR 140KW L&K
First Registrationdate:	24/05/2016	Fiscalpower:	DSG 4WD COMBI
Expertise Mileage:	186797	Power Kw:	140
Bodytype:		Body color	Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2114
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Seats R heated
GPS storage	HD	Seats electric F L
GPS storage		Seats electric F R
Windows electric F		Sun Roof electric
Windows electric R		Panoramic roof
Cruise Control		Central consol F
Steering wheel multifunctional		Luggage cover
Seats F heated		Front parking sensors
Type of headlighting	Headlighting Halogen	Rear parking sensors
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	
Adaptive cruise control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/55/17/94 W LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1039,23
-------------------	----------------

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02
---	---------------



Maintenance, Maintenance, Acceptable

0,00



Maintenance, Maintenance, Acceptable	0,00
--------------------------------------	------



Wing F L, Scratch(es), LI - Repair and paint (complete)	264,21
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Tailgate, Repaired, P - Check	0,00
-------------------------------	------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F L, Scratch(es), It - Spot repair	115,56
---	--------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Alloy rim F L, Damaged, E - Replace	277,44
-------------------------------------	--------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display