



BMW 5: 1FXV659

Vinnnumber:	WBA5J110X0D065306	Versionname:	5 TOURING 518dA 136PK Aut.
First Registrationdate:	2/12/2013	Fiscalpower:	
Expertise Mileage:	94996	Power Kw:	100
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1112
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Sun Roof electric
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining leather
Type of climate control:	Autom climate control
Head-up Display	

Limited Technical Inspection

Airco functioning:	OK	Battery functioning:	Yes
Tires wear profile:	OK	Power steering:	Yes
Idle position:	OK	Sound engine:	OK
Engine startingtime:	OK	Clutch test:	OK
Exhaust gass:	OK	Wiper fluid level:	OK
Handbrake:	OK	Transmission:	OK
		Lighting:	OK
		Wiperblades:	OK

Degree of wear

	25/55/17/95 W LightMetal			
Winter tyres:	Fr.L.	Kleber: 5 mm	Fr.R.	Kleber: 5 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
-------------	------------	-------------	------------

Total cost ex VAT:	2545,57
--------------------	----------------

Sill outer R, Scratch(es), LI - Repair and paint (complete):	468,60
--	---------------



Bumper R, Scratch(es), LI - Repair and paint (complete):	254,16
--	---------------

		
Front bumper, Scratch(es), LI - Repair and paint (complete)		254,16
		
Alloy rim R R, Scratch(es), Acceptable		0,00
No pictures to display		
Wing F L, Bump(s) and scratch(es), It - Spot repair		115,56
		
Wing R R, Scratch(es), LI - Repair and paint (complete)		369,84
		
Alloy rim R L, Scratch(es), Acceptable		0,00
No pictures to display		
Sill outer L, Scratch(es), LI - Repair and paint (complete)		372,60
		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Protection plate M, Strained , E - Replace		74,00
		
Alloy rim F R, Scratch(es), E - Replace		277,44
		
Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)		264,21
		
Door R L, Scratch(es), Acceptable		0,00

No pictures to display