



MAZDA CX-5: 1FGU419			
Vinnnumber:	JMZKEC97600212761	Versionname:	CX-5 4x2 Active 165PK
First Registrationdate:	25/06/2013	Fiscalpower:	
Expertise Mileage:	103765	Power Kw:	121
Bodytype:	SUV	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Petrol	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4831
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	225/65/17/102 V LightMetal			
	Fr.L.	Yokohama: 4 mm	Fr.R.	Yokohama: 4 mm
	Re.L.	Yokohama: 6 mm	Re.R.	Yokohama: 6 mm



Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	581,02
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Protection plate M, Strained , E - Replace	74,00



Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	

no pictures to display

Roof, Hail damage, PDR - Hail 125,00



Wing R R, Repaired, Acceptable 0,00

no pictures to display

Bumper R, Difference in color, Acceptable 0,00



Door R L, Scratch(es), LI - Repair and paint (complete) 382,02

