



VOLKSWAGEN Caddy: 1GQV632			
Vinnnumber:	WV1ZZZ2KZEX121383	Versionname:	CADDY VAN BlueMotion
First Registrationdate:	3/04/2014	Fiscalpower:	102PK
Expertise Mileage:	96270	Power Kw:	75
Bodytype:	Transporter	Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1106
Number of doors	5		
Number of seats	2		
Number head rests	2		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options		
Radio CD	Type of Tow bar	No Tow bar
Windows electric F		
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	195/65/15/91 H Steel			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Bridgestone: 4 mm	Re.R.	Bridgestone: 4 mm

Assistance equipment	
Total cost ex VAT	1655,98
Wheel cover R R, Scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror housing L, Scratch(es), Smart repair	110,64




Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)	232,88
---	--------





Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 231,15



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door panel R, Damaged, E - Replace 74,00




Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Rearlight R, Scratch(es), E - Replace 91,50




Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Bumper R, Scratch(es), Smart repair 110,64



Trunk door panel L, Damaged, E - Replace	74,00
	
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	231,15
  	
Wheel cover F R, Damaged, E - Replace	22,50
  	
 	
Roof, Bump(s), Acceptable	0,00
No pictures to display	