



FORD S Max: 1FFR247			
Vinnnumber:	WF0SXXGBWSD837455	Versionname:	S-MAX Titanium DPF
First Registrationdate:	17/06/2013	Fiscalpower:	136PK
Expertise Mileage:	168735	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1125
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options			
Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
	225/50/17/98 Y LightMetal		
Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.
	Re.L.	Michelin: 5 mm	Re.R.

Assistance equipment	
Total cost ex VAT	1906,41
Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	254,16



Tailgate, Scratch(es), LI - Repair and paint (complete)	362,02
---	--------

  			Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	264,21
 			Daytime running lights L, Damaged, E - Replace	20,00
 			Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
  			Alloy rim R R, Scratch(es), Acceptable	0,00
No pictures to display			Wing R L, Scratch(es), Acceptable	0,00
No pictures to display			Alloy rim F L, Scratch(es), Acceptable	0,00
No pictures to display			Door F L, Scratch(es), Acceptable	0,00
No pictures to display			Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	382,02
  			Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
  			Roof, Scratch(es), Acceptable	0,00
No pictures to display				