


**VOLVO V60: 1HFA971**

|                                   |                          |              |                                 |
|-----------------------------------|--------------------------|--------------|---------------------------------|
| Vinnnumber:                       | <b>YV1FW8481E1209014</b> | Versionname: | <b>V60 BRE D2 Kinetic 115PK</b> |
| First Registrationdate:           | <b>4/07/2014</b>         | Fiscalpower: |                                 |
| Expertise Mileage:                | <b>115574</b>            | Power Kw:    | <b>84</b>                       |
| Bodytype:                         | <b>Break</b>             | Body color   | <b>Black</b>                    |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>                  |
| Transmission:                     | <b>Front</b>             | Rims summer  | <b>Aluminium</b>                |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                       |
| Battery functioning               | <b>Yes</b>               | Parking lot  | <b>2315</b>                     |
| Number of doors                   | <b>5</b>                 |              |                                 |
| Number of seats                   | <b>5</b>                 |              |                                 |
| Number head rests                 | <b>5</b>                 |              |                                 |
| Rims summer                       | <b>Aluminium</b>         |              |                                 |
| Category                          | <b>Passenger Car</b>     |              |                                 |
| Oil level                         | <b>OK</b>                |              |                                 |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                                 |

**Options**

|                                |                              |                      |                   |
|--------------------------------|------------------------------|----------------------|-------------------|
| Radio CD                       |                              | Seats electric F L   |                   |
| GPS storage                    |                              | Central consol F     |                   |
| GPS storage                    | <b>HD</b>                    | Luggage cover        |                   |
| Windows electric F             |                              | Rear parking sensors |                   |
| Windows electric R             |                              | Type of Tow bar      | <b>No Tow bar</b> |
| Cruise Control                 |                              |                      |                   |
| Steering wheel multifunctional |                              |                      |                   |
| Seats F heated                 |                              |                      |                   |
| Radio multimedia               |                              |                      |                   |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |                   |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |                   |
| Type of Lining                 | <b>Lining leather</b>        |                      |                   |
| Type of climate control        | <b>Autom climate control</b> |                      |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                                  |                       |       |                       |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
|               | <b>215/50/17/95 W LightMetal</b> |                       |       |                       |
| Summer tyres: | Fr.L.                            | <b>Michelin: 7 mm</b> | Fr.R. | <b>Michelin: 7 mm</b> |
|               | Re.L.                            | <b>Pirelli: 5 mm</b>  | Re.R. | <b>Pirelli: 5 mm</b>  |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                                                             |               |
|-------------------------------------------------------------|---------------|
| Total cost ex VAT                                           | <b>929,88</b> |
| Front bumper, Scratch(es), Li - Repair and paint (complete) | <b>211,80</b> |



|                                               |               |
|-----------------------------------------------|---------------|
| Door F R, Dent(s) and scratch(es), Acceptable | <b>0,00</b>   |
| No pictures to display                        |               |
| Door panel F R, Hole, Smart repair            | <b>110,64</b> |



Alloy rim R L, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door panel F L, Hole, Smart repair 110,64



Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80





Wing F L, Dent(s), Acceptable

0,00

No pictures to display