



VOLKSWAGEN Golf: 1ESH216

Vinnnumber:	WVWZZZAUZDW089328	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	7/03/2013	Fiscalpower:	
Expertise Mileage:	137207	Power Kw:	77
Bodytype:		Body color	Blue
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2532
Number of doors	3		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options			
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	195/65/15/91 H Steel			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1008,66
Wheel cover F R, Scratch(es), Acceptable			0,00
No pictures to display			
Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)			406,50

Wheel cover R R, Scratch(es), Acceptable			0,00
No pictures to display			
Wing R L, Dent(s), Acceptable			0,00
No pictures to display			
Wing R R, Dent(s), Acceptable			0,00
No pictures to display			

Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rocker panel inner F L, Scratch(es), LI - Repair and paint (complete)	115,56
---	--------



Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R R, Dent(s), PDR - Knock out without painting	63,00
---	-------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------

