


VOLVO V40: 1GCV815

Vinnnumber:	YV1MV8481E2125109	Versionname:	V40 D2 Base 115PK
First Registrationdate:	3/01/2014	Fiscalpower:	
Expertise Mileage:	64239	Power Kw:	84
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2619
Maintenance	SERVICE IN 15194KM 8M		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Seats electric F L
GPS storage	Central consol F
GPS storage	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	Tow bar fixed
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/50/17/93 Y LightMetal			
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	3858,25
Foglight L, Deformed / Strained, E - Replace	138,00



Sill trim L, Scratch(es), LI - Repair and paint (complete)	310,50
--	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Outer door handle F R, Scratch(es), LI - Repair and paint (complete)

115,56



Door R R, Scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper trim R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair

110,64



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door frame F L, Dent(s), Acceptable	0,00
-------------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing F R, Dent(s), PDR - Knock out without painting	63,00
---	-------



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	452,20
---	--------



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Door F L, Chemical polution, LI - Repair and paint (complete)	318,35
---	--------



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

380,20

