



MERCEDES Sprinter 300: 235AMJ			
Vinnnumber:	WDB9062331N418213	Versionname:	SPRINTER CH2C 311
First Registrationdate:	29/04/2009	Fiscalpower:	3500kg MWB 109PK
Expertise Mileage:	77457	Power Kw:	80
Bodytype:		Body color	White
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Back	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	-225	Parking lot	TRU11
Maintenance	NOT OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	6		
Number head rests	6		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		

Options			
Windows electric F		Central consol F	
Type of headlighting	Headlighting Halogen	Type of Tow bar	No Tow bar
Type of Lining	Lining fabrics		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	No
Idle position	OK	Sound engine	NOT OK
Engine startingtime	NOT OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	NOT OK
		Lighting	OK
		Wiperblades	OK


Degree of wear			
Summer tyres:	235/65/16/107 R Steel		
	Fr.L.	Michelin: 7 mm	Fr.R.
	Re.L.	Michelin: 7 mm	Re.R.
		Michelin: 7 mm	Michelin: 7 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT			2291,98
Door R L, Rust, LI - Repair and paint (complete)			238,76



Door R R, Rust, LI - Repair and paint (complete)	238,76
--	--------





Instrument panel cover, Not functioning (well), E - Replace

45,00



Bumper grille, Broken, E - Replace

30,30



Seat cover F L, Worn, Acceptable

0,00



Maintenance, Maintenance, Execute

0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

165,13



Headlight L, Broken, E - Replace

321,00



Armrest R M, Damaged, E - Replace

120,00



Wing F L, Dent(s), Le - Replace and paint

427,51



Door F R, Rust, LI - Repair and paint (complete)

238,76





Handbrake cover, Tear, E - Replace	39,00
------------------------------------	-------



Instrument panel complete, Broken, E - Replace	10,00
--	-------



Cupholder, Missing, E - Replace	35,00
---------------------------------	-------



Gear shift lever cover, Tear, E - Replace	9,00
---	------



Door frame F R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door F L, Rust, LI - Repair and paint (complete)	238,76
--	--------



Inner seat cover R, Missing, E - Replace	10,00
--	-------



Grill, Broken, E - Replace	125,00
----------------------------	--------

