



BMW 3: 1HHL035

Vinnumber:	WBA3K11060F834411	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	24/07/2014	Fiscalpower:	
Expertise Mileage:	61985	Power Kw:	100
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	24000	Parking lot	2831
Maintenance	NOVEMBER 2019		
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar fixed
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS base		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/92 W LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	-----	------------	-----

Total cost ex VAT	830,88
-------------------	--------

Door R R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>		
Wing R R, Dent(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Wing R L, Dent(s) and scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Roof, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door panel F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door F L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bonnet, Stone chip(s), Acceptable		0,00
<i>No pictures to display</i>		
Door panel trim R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door frame R R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Ceiling, Dirty, Acceptable		0,00
<i>No pictures to display</i>		
Wing F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Bumper R, Dent(s) and scratch(es), Le - Replace and paint		651,00



Alloy rim R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Door R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Sill trim L, Scratch(es), It - Spot repair		115,56



Outer backrest protection R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door panel F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Outer door handle F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Floor covering F L, Worn, Smart repair	64,32
	
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Outer backrest protection L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Boot carpet, Stain, Acceptable	0,00
<i>No pictures to display</i>	
Seat F L compl, Worn, Acceptable	0,00
<i>No pictures to display</i>	
Door panel R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	