


SKODA Superb: 1HXL457

Vinnumber:	TMBJJ73T9F9023054	Versionname:	SUPERB COMBI GreenLine Elegance 105PK
First Registrationdate:	22/10/2014	Fiscalpower:	
Expertise Mileage:	84466	Power Kw:	77
Bodytype:	Break	Body color:	Black
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2428
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Seats electric F L
Windows electric F	Sun Roof electric
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	No Tow bar
Type of GPS	Headlighting Xenon
Type of Lining	GPS big screen color
Type of climate control	Lining leather
	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.
	Re.L.	Continental: 5 mm	Re.R.
		Continental: 4 mm	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			2084,23
Door F R, Scratch(es), Acceptable			0,00
No pictures to display			
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00



Wing F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Rust, LI - Repair and paint (complete)	382,02
--	--------



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	264,21
---	--------



Wing R R, Scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	369,84
---	--------



Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------

