


AUDI A6: 1GRJ636

Vinnumber:	WAUZZZ4G6EN119574	Versionname:	A6 AVANT 136PK
First Registrationdate:	8/04/2014	Fiscalpower:	
Expertise Mileage:	119704	Power Kw:	100
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3112
Maintenance	OVER 6100KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/17/97 H LightMetal			
Winter tyres:	Fr.L.	Uniroyal: 5 mm	Fr.R.	Uniroyal: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1147,48
Bonnet, Stone chip(s), Acceptable			0,00



Bumper F, Scratch(es), Acceptable

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Chemical pollution, Acceptable

0,00



Wing R L, Dent(s) and scratch(es), Acceptable

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00



Wing R R, Bad repair, LI - Repair and paint (complete)

369,84



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Scratch(es), Acceptable

0,00



Floor covering F L, Burned, Smart repair

64,32



Tyre F L, Tear, E - Replace

153,60



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Door R R, Chemical polution, Acceptable

0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16

