



VOLKSWAGEN Golf: 1GGS749

Vinnumber:	WVWZZZAUZEP549582	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	4/02/2014	Fiscalpower:	
Expertise Mileage:	135420	Power Kw:	77
Bodytype:	Break	Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	BINNEN 14600 KM	Parking lot:	3209
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Adaptive cruise control			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Firestone: 7 mm	Fr.R.
	Re.L.	Continental: 5 mm	Re.R.

Assistance equipment

Total cost ex VAT	1155,84
Door F R, Repaired, No repair	0,00



Interior, Dirty, Cleaning

125,00



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s), Acceptable

0,00

No pictures to display

Windscreen, Repaired, E - Replace

487,20



Door R R, Repaired, No repair

0,00



Rear window, Scratch(es), E - Replace

370,00



Tailgate, Dent(s), Acceptable

0,00

No pictures to display

Rearview mirror housing L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel covers F R, Scratch(es), Acceptable

0,00

Wheel cover F R, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Dent(s), PDR - Paintless dent repair	63,00
	
Wing R R, Repaired, No repair	0,00
	
Wheel cover R R, Scratch(es), Acceptable	0,00
No pictures to display	
Roof, Dent(s), Acceptable	0,00
No pictures to display	
Trunk lid covering R, Scratch(es), Smart repair	110,64
	
Wing F R, Repaired, No repair	0,00
	
Bumper corner R L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	