



# BMW 3 TOURING: 1KHG848

|                                   |                   |              |                          |
|-----------------------------------|-------------------|--------------|--------------------------|
| Vinnumber:                        | WBA3K11090F839215 | Versionname: | 2.0 318D (100KW) TOURING |
| First Registrationdate:           | 5/05/2015         | Fiscalpower: |                          |
| Expertise Mileage:                | 105822            | Power Kw:    | 100                      |
| Bodytype:                         | Break             | Body color   | Dark Grey                |
| Gearbox:                          | MAN 6 VIT         | Paint type   | Metalic                  |
| Transmission:                     | Back              | Rims summer  | Aluminium                |
| Fueltype:                         | Diesel            | Oil level    | OK                       |
| Battery functioning               | Yes               | Parking lot  | 1304                     |
| Number of doors                   | 5                 |              |                          |
| Number of seats                   | 5                 |              |                          |
| Number head rests                 | 5                 |              |                          |
| Rims summer                       | Aluminium         |              |                          |
| Category                          | Passenger Car     |              |                          |
| Oil level                         | OK                |              |                          |
| Registration Certificate Car (BE) | Yes               |              |                          |

## Options

|                                |                         |
|--------------------------------|-------------------------|
| Radio CD                       | Central consol F        |
| GPS storage                    | Luggage cover           |
| GPS storage                    | HD Rear parking sensors |
| Windows electric F             | Type of Tow bar         |
| Windows electric R             | No Tow bar              |
| Cruise Control                 |                         |
| Steering wheel multifunctional |                         |
| Radio multimedia               |                         |
| Type of headlighting           | Headlighting Halogen    |
| Type of GPS                    | GPS big screen color    |
| Type of Lining                 | Lining fabrics          |
| Type of climate control        | Autom climate control   |

## Limited Technical Inspection

|                     |    |                     |     |
|---------------------|----|---------------------|-----|
| Airco functioning   | OK | Battery functioning | Yes |
| Tires wear profile  | OK | Power steering      | Yes |
| Idle position       | OK | Sound engine        | OK  |
| Engine startingtime | OK | Clutch test         | OK  |
| Exhaust gass        | OK | Wiper fluid level   | OK  |
| Handbrake           | OK | Transmission        | OK  |
|                     |    | Lighting            | OK  |
|                     |    | Wiperblades         | OK  |

## Degree of wear

|               |                           |                |       |                |
|---------------|---------------------------|----------------|-------|----------------|
| Summer tyres: | 205/60/16/92 W LightMetal |                |       |                |
|               | Fr.L.                     | Michelin: 5 mm | Fr.R. | Michelin: 5 mm |
|               | Re.L.                     | Michelin: 5 mm | Re.R. | Michelin: 5 mm |

## Assistance equipment

|                                          |     |            |     |
|------------------------------------------|-----|------------|-----|
| Repair kit                               | Yes | Compressor | Yes |
| Number of charging cables (normal)       | 0   |            |     |
| Number of charging cables (rapid charge) | 0   |            |     |

|                   |        |
|-------------------|--------|
| Total cost ex VAT | 496,80 |
|-------------------|--------|

|                                               |      |
|-----------------------------------------------|------|
| Wing F R, Dent(s) and scratch(es), Acceptable | 0,00 |
|-----------------------------------------------|------|

No pictures to display

|                             |      |
|-----------------------------|------|
| Bonnet, Dent(s), Acceptable | 0,00 |
|-----------------------------|------|

No pictures to display

|                                  |      |
|----------------------------------|------|
| Door R R, Bad repair, Acceptable | 0,00 |
|----------------------------------|------|



|                                                         |        |
|---------------------------------------------------------|--------|
| Bumper R, Scratch(es), LI - Repair and paint (complete) | 211,80 |
|---------------------------------------------------------|--------|



|                                                              |       |
|--------------------------------------------------------------|-------|
| Alloy rim F L, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|-------|



|                                   |      |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                  |      |
|----------------------------------|------|
| Bumper F, Bad repair, Acceptable | 0,00 |
|----------------------------------|------|



|                                   |      |
|-----------------------------------|------|
| Door F R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                                              |       |
|--------------------------------------------------------------|-------|
| Alloy rim R R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|-------|






|                                                                     |      |
|---------------------------------------------------------------------|------|
| Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) | 0,00 |
|---------------------------------------------------------------------|------|



|                                                     |      |
|-----------------------------------------------------|------|
| Roof, Scratch(es), LI - Repair and paint (complete) | 0,00 |
|-----------------------------------------------------|------|



|                                        |      |
|----------------------------------------|------|
| Alloy rim R L, Scratch(es), Acceptable | 0,00 |
|----------------------------------------|------|

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Wing F L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                                              |       |
|--------------------------------------------------------------|-------|
| Alloy rim F R, Scratch(es), LI - Repair and paint (complete) | 95,00 |
|--------------------------------------------------------------|-------|



|                               |      |
|-------------------------------|------|
| Wing R L, Dent(s), Acceptable | 0,00 |
|-------------------------------|------|

No pictures to display