


TOYOTA Auris: 1HHP077

Vinnumber:	SB1ZS3JE20E097643	Versionname:	AURIS TOUR.SP.HSD Dynamic CVT 99PK Aut.
First Registrationdate:	25/07/2014	Fiscalpower:	
Expertise Mileage:	143399	Power Kw:	73
Bodytype:		Body color	White
Gearbox:	Automatic	Paint type	Opaque
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Hybrid Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	3731
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Type of Tow bar	No Tow bar
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	522,30
-------------------	---------------

Bodywork, Not original part, Acceptable	0,00
---	-------------

No pictures to display

Alloy rim F R polished, Scratch(es), Acceptable	0,00
---	-------------

No pictures to display

Bonnet, Dent(s), Acceptable	0,00
-----------------------------	-------------

No pictures to display

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	310,50
---	--------



Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing R L, Bad repair, Acceptable	0,00
----------------------------------	------

