



VOLKSWAGEN PASSAT VARIANT: 1LCB679

Vinnumber:	WVWZZZ3CZGE021882	Versionname:	1.6 TDI VARIANT COMFORTLINE
First Registrationdate:	17/08/2015	Fiscalpower:	
Expertise Mileage:	133964	Power Kw:	88
Bodytype:	Break	Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2425
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Windows electric R	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/60/16/99 H LightMetal			
	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2575,81
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Door R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display


Rocker panel inner F L, Dent(s), Acceptable

0,00

No pictures to display


Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80




Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Windscreen, Stone chip(s), Acceptable

0,00



Luggage space cover, Scratch(es), Smart repair

110,64




Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

301,68



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Sill outer R, Scratch(es), Acceptable

0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair

110,64



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display