


RENAULT CAPTUR: 1KAZ143

Vinnumber:	VF12R5A1H52604079	Versionname:	0.9 TCE 90 ENERGY INTENS ECO2
First Registrationdate:	23/03/2015	Fiscalpower:	
Expertise Mileage:	40502	Power Kw:	66
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	1119
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Windows electric F	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Rear parking sensors	
Steering wheel multifunctional	Type of Tow bar	No Tow bar
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/17/95 V LightMetal			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1979,10
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	246,56



Bumper R, Crack, E - Replace

346,66



Door R L, Scratch(es), LI - Repair and paint (complete)

254,68



Ignition key, Missing, E - Replace

150,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)

337,34



Bumper corner R R, Dent(s) and scratch(es), It - Spot repair

115,66



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Alloy rim F R polished, Rust, Acceptable

0,00

No pictures to display

Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper grille, Scratch(es), E - Replace

30,72



Windscreen, R R, Scratch(es), E - Replace

64,88

Wheel arch cover R R, Scratch(es), E - Replace

64,00



Rearview mirror housing R, Broken, E - Replace

84,00

