



VOLKSWAGEN Crafter 35 MWB: 1BEM313

Vinnumber:	WV1ZZZ2FZB7005554	Versionname:	CRAFTER 35 LB2C MWB 109PK
First Registrationdate:	12/05/2011	Fiscalpower:	
Expertise Mileage:	151145	Power Kw:	80
Bodytype:	Transporter	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	LCV21
Number of doors	4		
Number of seats	7		
Number head rests	7		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining artificial leather	
Type of climate control	No climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	235/65/16/115 R Steel			
	Fr.L.	Kumho: 4 mm	Fr.R.	Kumho: 4 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare wheel	Yes
Total cost ex VAT	2178,18
Door R L, Rust, LI - Repair and paint (complete)	238,76





Wheel cover R L, Missing, E - Replace

22,50



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Door panel R L, Broken, E - Replace

91,50



Wheel cover F L, Missing, E - Replace

22,50



Bumper F, Scratch(es), Smart repair

110,64



Seat cover F R, Tear, E - Replace

300,00



Door R R, Rust, LI - Repair and paint (complete)

238,76



Protection plate M, Tear, E - Replace

74,00



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

232,88



Boot carpet, Hole, E - Replace

75,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Sill outer L, Rust, LI - Repair and paint (complete)

232,88



Seat cover F L, Damaged, E - Replace

300,00

