



VOLKSWAGEN Golf: GG6927

Vinnumber:	WVWZZZAUZEW398636	Versionname:	GOLF BER GTD 184PK
First Registrationdate:	16/05/2014	Fiscalpower:	
Expertise Mileage:	174314	Power Kw:	135
Bodytype:	Hatchback	Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4731
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Tow bar fixed
Type of GPS	Headlighting Xenon
Type of Lining	No GPS
Type of climate control	Lining fabrics
Sport seats	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/45/18/92 Y LightMetal			
	Fr.L.	Continental: 2 mm	Fr.R.	Continental: 2 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2701,26
Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)	115,56



Bonnet, Stone chip(s), Acceptable

0,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

404,20





Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Broken, Le - Replace and paint 735,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 462,35



Rear window, Scratch(es), Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Windscreen, Stone chip(s), Acceptable

0,00

No pictures to display

Protection plate M, Missing, E - Replace

74,00



Trunk lid covering R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display