



VOLKSWAGEN Touran: 1GIF734

Vinnumber:	WVGZZZ1TZEW049702	Versionname:	TOURAN Trendline BMT St&St 7pl.105PK
First Registrationdate:	15/01/2014	Fiscalpower:	
Expertise Mileage:	112080	Power Kw:	77
Bodytype:	MPV	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4820
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	Type of Tow bar
Windows electric R	No Tow bar
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1275,10
Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	220,18



Door R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00



Roof, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Rocker panel inner R R, Dent(s), LI - Repair and paint (complete) 115,56



Roof pillar R, Scratch(es), Acceptable 0,00

No pictures to display

Shutter / cover, Missing, E - Replace 32,00



Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar L, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel hub cap F L, Missing, E - Replace	49,40
	
Bonnet, Stone chip(s), Acceptable	0,00
No pictures to display	
Door trim F L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R polished, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00
	
Outer door handle F L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
	
Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
	
Alloy rim F L polished, Scratch(es), Acceptable	0,00
	



Door frame R R, Dent(s), It - Spot repair

115,56



Door R L, Dent(s) and scratch(es), Acceptable

0,00



Outer door handle F R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper grille, Broken, E - Replace

32,40



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Wing R L, Dent(s), Acceptable

0,00

