



PEUGEOT 308 SW: 1LVK324

Vinnumber:	VF3LCBHXHFS334062	Versionname:	1.6 BLUEHDI 85KW S/S 88G ALLURE
First Registrationdate:	16/12/2015	Fiscalpower:	
Expertise Mileage:	172560	Power Kw:	85
Bodytype:	Break	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2815
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	
Type of GPS	Headlighting LED
Type of Lining	GPS big screen color
Type of climate control	Lining fabrics
	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 V LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Compressor	Yes
------------	------------

Total cost ex VAT	1396,62
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00





Sill outer R, Scratch(es), LI - Repair and paint (complete)

310,50



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00



Interior, Dirty, Cleaning

50,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Door R R, Scratch(es), 67 - Polish

0,00

No pictures to display

Instruction book, Missing, E - Replace

0,00

No pictures to display

Wing R R, Scratch(es), 67 - Polish

0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete)

308,20



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Maintenance book, Missing, E - Replace

0,00

No pictures to display

Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)		115,56
		
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80
		
Bumper F, Stone chip(s), Acceptable		0,00
No pictures to display		
Bodywork, Not original part, Acceptable		0,00
No pictures to display		