



BMW X5: 1GAE635

Vinnumber:	WBAKS410000C35393	Versionname:	X5 3.0dA xDrive30 258PK Aut.
First Registrationdate:	4/12/2013	Fiscalpower:	
Expertise Mileage:	156990	Power Kw:	190
Bodytype:		Body color	Dark Brown
Gearbox:	Automatic	Paint type	Metalic
Transmission:	4 Weel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3311
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Seats electric F L
TV/DVD screen R	Seats electric F R
GPS storage	Central consol F
GPS storage	HD Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	Tow bar fixed
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	255/50/19/107 W LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT	687,58
Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00



Bumper R, Scratch(es), Acceptable	0,00
No pictures to display	
Door F R, Repaired, Acceptable	0,00
No pictures to display	
Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	
Rear window, Scratch(es), Acceptable	0,00



Door R R, Repaired, Acceptable	0,00
No pictures to display	
Bonnet, Chemical polution, 67 - Polish	0,00
No pictures to display	
Wing R R, Bad repair, Acceptable	0,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------




Wing F L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00





Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)

115,56



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Repaired, Acceptable

0,00

