



VOLKSWAGEN GOLF VII: 1LNB523

Vinnumber:	WVWZZZAUZGP052124	Versionname:	1.6 TDI 81KW TRENDLINE
First Registrationdate:	26/10/2015	Fiscalpower:	
Expertise Mileage:	89087	Power Kw:	81
Bodytype:	Hatchback	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3514
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Front parking sensors
Windows electric F	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	-----	------	-----

Total cost ex VAT	758,58
-------------------	--------

Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display	
Trunk lid covering R, Scratch(es), Acceptable	0,00

No pictures to display	
Mats, Burned, Acceptable	0,00

No pictures to display	
------------------------	--

No pictures to display

Windscreen, Stone chip(s), P - Check	0,00
--------------------------------------	------



Door F L, Scratch(es), It - Spot repair	115,56
---	--------



Wheel cover F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Seat cover F R, Stain, Acceptable	0,00
-----------------------------------	------

No pictures to display

Boot cover, Missing, E - Replace	155,10
----------------------------------	--------



Seat cover F L, Stain, Acceptable	0,00
-----------------------------------	------

No pictures to display

Bonnet, Dent(s), PDR - Paintless dent repair	63,00
--	-------



Rearview mirror basis L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Wheel cover F R, Scratch(es), E - Replace	30,00
---	-------



Seat cover R, Stain, Cleaning	25,00
-------------------------------	-------



Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Door panel F L, Stain, Cleaning	25,00
---------------------------------	-------



Door panel F R, Stain, Cleaning	25,00
---------------------------------	-------

Bumper F R, Scratch(es), It - Spot repair	115,56
---	--------



Door R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wheel cover R R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Ceiling, Stain, Cleaning	0,00
--------------------------	------



Steel rim F R, Deformed / Strained, E - Replace	88,80
---	-------



Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

No pictures to display

Boot carpet, Stain, Cleaning	25,00
------------------------------	-------

