



BMW 1 HATCH: 1LHE492

Vinnumber:	WBA1V910805B19362	Versionname:	1.5 116D EFFICIENTDYNAMICS EDIT. (85KW)
First Registrationdate:	28/09/2015	Fiscalpower:	
Expertise Mileage:	65571	Power Kw:	85
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3511
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 T LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1936,65
Door F R, Dent(s) and scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00



Windscreen, Stone chip(s), Acceptable

0,00



Bumper F, Broken, Le - Replace and paint

735,00



Roof, Chemical polution, LI - Repair and paint (complete)

481,50



Door R L, Scratch(es), 67 - Polish

0,00

No pictures to display

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Gear shift lever knob, Worn, Acceptable

0,00



Door panel R L, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R L, Scratch(es), 67 - Polish	0,00
No pictures to display	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Wing R R, Scratch(es), 67 - Polish	0,00
No pictures to display	
Rear window, Scratch(es), Acceptable	0,00



Alloy rim R L, Scratch(es), Acceptable	0,00
No pictures to display	