



FORD Fiesta: 1HEJ598

Vinnumber:	WF0DXXGAKDEU88874	Versionname:	FIESTA BER EcoBoost Titanium S/S 125PK
First Registrationdate:	1/07/2014	Fiscalpower:	
Expertise Mileage:	58088	Power Kw:	92
Bodytype:		Body color	Blue
Gearbox:	MAN 5 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	2704
Number of doors	5		
Number of seats	5		
Number head rests	4		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	SD Rear parking sensors
Windows electric F	Type of Tow bar
Cruise Control	No Tow bar
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/50/15/82 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Hankook: 5 mm	Re.R.	Hankook: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1813,00
-------------------	---------

Wing F R, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display	
------------------------	--

Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display	
------------------------	--

Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Bonnet, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Scratch(es), LI - Repair and paint (complete)

246,56



Rear window, Scratch(es), Acceptable

0,00




Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Wing F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
	
Wing R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
	
Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)	254,68
	
Bumper F, Scratch(es), LI - Repair and paint (complete)	169,44
	
Roof, Chemical polution, LI - Repair and paint (complete)	433,20



Door F L, Scratch(es), Acceptable

0,00

No pictures to display