


BMW 2 Active Tourer: 1HYE170

Vinnumber:	WBA2C11050VZ54764	Versionname:	2 ACTIVE TOURER 218d 136PK
First Registrationdate:	28/10/2014	Fiscalpower:	
Expertise Mileage:	115688	Power Kw:	100
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4120
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Sun Roof electric	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	205/60/16/92 H LightMetal			
Winter tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Number of charging cables (normal)	0	Runflat	Yes
Number of charging cables (rapid charge)	0		

Total cost ex VAT		1944,93
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)		318,35



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Wing F L, Chemical polution, 67 - Polish

0,00

No pictures to display

Boot cover, Broken, E - Replace

50,00



Alloy rim F L, Scratch(es), Acceptable

0,00

No pictures to display

Rearview mirror basis L, Scratch(es), Smart repair

110,64



Wing R L, Scratch(es), 67 - Polish

0,00

No pictures to display

Wing F R, Scratch(es), Acceptable

0,00

No pictures to display


Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Bumper, Chemical polution, LI - Repair and paint (complete)

200,00



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Rear spoiler, Dent(s), LI - Repair and paint (complete)

115,56



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35

