


OPEL INSIGNIA SPORTS TOURER: 1PDD381

Vinnumber:	W0LGT8E30G1090647	Versionname:	1.6 CDTI ECOFLEX 100KW S/S COSMO
First Registrationdate:	8/06/2016	Fiscalpower:	
Expertise Mileage:	101276	Power Kw:	100
Bodytype:		Body color	Blue
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1522
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Sun Roof electric	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	245/45/18/96 W LightMetal			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1296,63
Door R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Floor covering F L, Worn, Acceptable	0,00




Wing F R, Scratch(es), LI - Repair and paint (complete)

0,00



Bonnet, Chemical polution, LI - Repair and paint (complete)

290,08



Tailgate, Scratch(es), Acceptable

0,00

No pictures to display

Windscreen, Repaired, Acceptable

0,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Rear window, Scratch(es), E - Replace

0,00



Backrest cover F L, Worn, Acceptable

0,00



Door F R, Scratch(es), LI - Repair and paint (complete)		318,35
		
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Bumper R, Scratch(es), Acceptable		0,00
No pictures to display		
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)		308,20
		
Door R R, Scratch(es), LI - Repair and paint (complete)		0,00
		
Roof, Chemical polution, 67 - Polish		0,00
No pictures to display		
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)		95,00
		
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)		95,00



Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	