



VOLVO V40: 1FGZ761			
Vinnumber:	YV1MV8481E2084929	Versionname:	V40 D2 Base 115PK
First Registrationdate:	26/06/2013	Fiscalpower:	
Expertise Mileage:	102454	Power Kw:	84
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4720
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		


Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1443,06
Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	

Alloy rim R L, Scratch(es), Acceptable	0,00
No pictures to display	
Windscreen, Scratch(es), Acceptable	0,00
	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F L, Scratch(es), Acceptable	0,00
No pictures to display	
Rear window, Scratch(es), Acceptable	0,00
	
Wing R R, Dent(s), PDR - Paintless dent repair	63,00
	
Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete)	301,68
	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
	
Roof, Chemical polution, LI - Repair and paint (complete)	481,50
	
Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	
Rearview mirror housing L, Scratch(es), 67 - Polish	0,00
No pictures to display	
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

