



FORD S-MAX: 1LVF566

Vinnumber:	WF0JXXWPCJFM55587	Versionname:	2.0 TDCI 110KW S/S BUSINESS ED+
First Registrationdate:	15/12/2015	Fiscalpower:	
Expertise Mileage:	143481	Power Kw:	110
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2311
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L
GPS storage	SD	Seats electric F R
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Rear parking sensors
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	235/55/17/99 H LightMetal			
Winter tyres:	Fr.L.	Dunlop: 4 mm	Fr.R.	Dunlop: 4 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	1737,61
Foglight L, Missing, E - Replace	156,00



Mirror side blinker L, Waterinfiltration, E - Replace

31,20



Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09



Mirror side blinker R, Scratch(es), E - Replace

31,20



Door R L, Bad repair, Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

254,16



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

254,16



Roof, Chemical polution, LI - Repair and paint (complete)

577,80



Wing R R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Door F R, Dent(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Molding trunk, Damaged, E - Replace	85,00
-------------------------------------	-------

