



PEUGEOT 508: 1EEJ981			
Vinnnumber:	VF38D4HLACL078291	Versionname:	508 BER GT 204PK Aut.
First Registrationdate:	7/11/2012	Fiscalpower:	
Expertise Mileage:	111523	Power Kw:	150
Bodytype:		Body color	White
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3505
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Central consol F
Cruise Control	Luggage cover
Steering wheel multifunctional	Front parking sensors
Seats F heated	Rear parking sensors
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining semi-leather
Type of climate control	Autom climate control
Head-up Display	

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Sound engine	OK
Idle position	OK	Clutch test	OK
Engine startingtime	OK	Wiper fluid level	OK
Exhaust gass	OK	Lighting	OK
Transmission	OK	Wiperblades	OK
Handbrake	OK		

Degree of wear				
Winter tyres:	235/45/18/98 V LightMetal			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1423,60
Ignition key, Missing, E - Replace			150,00
No pictures to display			
Rearview mirror housing R, Scratch(es), Acceptable			0,00
No pictures to display			
Bonnet, Scratch(es), Acceptable			0,00
No pictures to display			
Alloy rim R L, Scratch(es), LI - Repair and paint (complete)			95,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)		95,00	
--	--	-------	--



Headlight L, Scratch(es), E - Replace	396,00
---------------------------------------	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Protection plate M, Tear, E - Replace	74,00
---------------------------------------	-------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

