



PEUGEOT 5008: 1ENA727			
Vinnnumber:	VF30E9HD8CS265228	Versionname:	5008 Allure FAP 115PK
First Registrationdate:	28/01/2013	Fiscalpower:	
Expertise Mileage:	84474	Power Kw:	84
Bodytype:	MPV	Body color	Dark Red
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4626
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Panoramic roof
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Head-up Display	

Limited Technical Inspection			
Power steering	Yes	Battery functioning	Yes
Airco functioning	OK	Sound engine	OK
Tires wear profile	OK	Clutch test	OK
Idle position	OK	Wiper fluid level	OK
Engine startingtime	OK	Lighting	OK
Exhaust gass	OK	Wiperblades	OK
Transmission	OK		
Handbrake	OK		

Degree of wear				
Winter tyres:	215/60/19/596 V LightMetal			
	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment	
Total cost ex VAT	3776,43
Trunk lid covering R, Damaged, E - Replace	74,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Interior, Dirty, Cleaning

100,00



Sill outer R, Bump(s) and scratch(es), LI - Repair and paint (complete)

406,50



Covering interior front pillar R, Scratch(es), Smart repair

110,64



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)

301,68



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Door R L, Scratch(es), LI - Repair and paint (complete)

318,35



Wing R R, Scratch(es), LI - Repair and paint (complete)

308,20



Bonnet, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer L, Bump(s) and scratch(es), LI - Repair and paint (complete)

406,50



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Front bumper, Damaged, Le - Replace and paint	735,00
---	--------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

