


TOYOTA AURIS: 1JTP511

Vinnnumber:	SB1MS3JE20E148505	Versionname:	1.8 HYBRID PREMIUM CVT AUTO
First Registrationdate:	23/02/2015	Fiscalpower:	
Expertise Mileage:	42237	Power Kw:	100
Bodytype:		Body color	Blue
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Hybrid Petrol	Oil level	OK
Maintenance	LAATSTE ONDERHOUD OP 42221KM 3 2018	Parking lot	3511
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L
GPS storage	HD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/45/17/91 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment


Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------


Total cost ex VAT	917,16
Wing R R, Scratch(es), It - Spot repair	115,56



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00

			95,00
			211,80
			0,00
			0,00
No pictures to display			
Wing R L, Scratch(es), Acceptable			0,00
No pictures to display			
Bumper R, Scratch(es), LI - Repair and paint (complete)			211,80
			0,00
No pictures to display			
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)			95,00
			0,00
			63,00
			



Mirror side blinker L, Crack, E - Replace

30,00

