



RENAULT Clio: 1GWL648

Vinnnumber:	VF15RJL0H50895037	Versionname:	CLIO IV BER e-Expression St&St 90PK
First Registrationdate:	20/05/2014	Fiscalpower:	
Expertise Mileage:	81772	Power Kw:	66
Bodytype:		Body color:	Silver
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3510
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	4		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Cruise Control	
Steering wheel multifunctional	
Alarm	
Type of headlighting:	Headlighting Halogen
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	185/65/15/88 T Steel			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

















Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 820,20

Wheel cover R R, Damaged, E - Replace 24,00



Door panel F R, Damaged, Smart repair 110,64

			Bodywork, Not original part, Acceptable	0,00
			Door frame R L, Bump(s) and scratch(es), It - Spot repair	115,56
			Wheel cover F R, Damaged, E - Replace	24,00
			Wheel cover F L, Damaged, E - Replace	24,00
			Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	169,44
			Rear window, Scratch(es), Acceptable	0,00
No pictures to display				
			Front bumper, Scratch(es), Acceptable	0,00
No pictures to display				
Ignition key, Missing, E - Replace				150,00
No pictures to display				
			Tailgate, Scratch(es), Acceptable	0,00
No pictures to display				
			Door frame F L, Bump(s) and scratch(es), It - Spot repair	115,56
			Door F L, Bump(s), PDR - Knock out without painting	63,00



Wheel cover R L, Damaged, E - Replace 24,00

