



TOYOTA Auris: 1GA1021

Vinnnumber:	SB1ZS3JE70E060054	Versionname:	AURIS TOUR.SP. HSD
First Registrationdate:	5/12/2013	Fiscalpower:	Comfort CVT 99PK Aut.
Expertise Mileage:	179941	Power Kw:	73
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Hybrid Petrol	Oil level	OK
Maintenance	OK	Parking lot	3503
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT		896,72	
Bumper R, Scratch(es), Acceptable		0,00	

No pictures to display	
Bonnet, Bump(s) and scratch(es), LI - Repair and paint (complete)	290,08





Door panel R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display


Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Wing R L, Bump(s), PDR - Knock out without painting	63,00
---	-------



Rear window, Scratch(es), E - Replace	370,00
---------------------------------------	--------



Internal Boot Lining L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door panel R R, Scratch(es), Smart repair	110,64
---	--------



Sill outer R, Strained , I - Repair	0,00
-------------------------------------	------



Door R L, Bump(s), PDR - Knock out without painting	63,00
---	-------

