



TOYOTA YARIS: YX7376

Vinnumber:	VNKKD3D350A282219	Versionname:	1.5 VVT-I HYBRID DYNAMIC AUTO
First Registrationdate:	12/01/2017	Fiscalpower:	
Expertise Mileage:	42815	Power Kw:	74
Bodytype:		Body color	Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Hybrid Petrol	Oil level	OK
Maintenance	OK	Parking lot	3511
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options			
GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	175/65/15/88 T Steel			
	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1270,36
Bumper R, Scratch(es), LI - Repair and paint (complete)			169,44






Bumper F, Scratch(es), LI - Repair and paint (complete)

169,44



Door F R, Scratch(es), LI - Repair and paint (complete)

254,68



Wheel cover R R, Scratch(es), E - Replace

24,00



Wheel cover F L, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

246,56



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer R, Scratch(es), It - Spot repair

115,56



Wing F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper spoiler F, Missing, E - Replace

36,00



Door R R, Scratch(es), LI - Repair and paint (complete)

254,68



