


VOLKSWAGEN Golf: 1.8D 103

Vinnnumber:	WVWZZZ1KZBW310016	Versionname:	GOLF BER Highline DPF
First Registrationdate:	10/05/2011	Fiscalpower:	DSG 140PK
Expertise Mileage:	56070	Power Kw:	103
Bodytype:		Body color	Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	GEEN MELDING	Parking lot	3611
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Sun Roof electric
GPS storage	Central consol F
GPS storage	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	Type of Tow bar
Steering wheel multifunctional	No Tow bar
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Dunlop: 6 mm	Re.R.	Dunlop: 6 mm

Assistance equipment


Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1926,29
-------------------	----------------

Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20
---	---------------



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---------------

		Wing F R, Dent(s), PDR - Knock out without painting	87,00
		Door R R, Dent(s), PDR - Knock out without painting	63,00
		Door F R, Scratch(es), Acceptable	0,00
No pictures to display			
		Door panel R L, Hole, Smart repair	110,64
		Bumper F, Scratch(es), LI - Repair and paint (complete)	211,80
		Rearlight L, Broken, E - Replace	114,00
		Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80
		Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)	406,50



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

