



peugeot partner: 1EBV718			
Vinnnumber:	VF37A9HXCBJ515800	Versionname:	
First Registrationdate:	20/06/2011	Fiscalpower:	
Expertise Mileage:	234032	Power Kw:	66
Bodytype:		Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	4403
Number of doors	5		
Number of seats	2		
Number head rests	2		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		

Options	
Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	195/65/15/91 T Steel			
	Fr.L.	Vredestein: 6 mm	Fr.R.	Vredestein: 6 mm
	Re.L.	Vredestein: 6 mm	Re.R.	Vredestein: 6 mm

Assistance equipment			
Spare wheel	Yes	Jack	Yes
Total cost ex VAT		2833,80	
Radio, Broken, E - Replace		210,00	



Bodywork, Not original part, Acceptable	0,00
---	------





Bumper F, Scratch(es), E - Replace 418,56



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 294,56



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 254,68



Trunk door R R, Scratch(es), Acceptable 0,00



Rearview mirror housing R, Crack, LI - Repair and paint (complete) 115,56



Bumper corner R R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 296,40



Ignition key, Not functioning (well), E - Replace 150,00



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete) 248,40



Rearlight R tailgate, Broken, E - Replace 99,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 350,68



Trunk door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door moulding Lower F R, Broken, E - Replace 96,00



Number plate light L, Missing, E - Replace 34,40



Trunk door R R, Dent(s) and scratch(es), It - Spot repair 115,56



Ignition key, Missing, E - Replace 150,00

