



TOYOTA YARIS: HP5251

Vinnumber:	VNKKD3D300A234868	Versionname:	1.5 VVT-I HYBRID DYNAMIC AUTO
First Registrationdate:	29/04/2016	Fiscalpower:	
Expertise Mileage:	72087	Power Kw:	74
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Hybrid Petrol	Oil level	OK
Maintenance	OK	Parking lot	3722
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	HD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	175/65/15/84 H Steel			
	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Dunlop: 5 mm	Re.R.	Dunlop: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2554,10
Wheel cover F R, Scratch(es), Acceptable	0,00

No pictures to display

Wing F L, Scratch(es), LI - Repair and paint (complete)	176,14
---	--------



Wheel cover F L, Scratch(es), E - Replace

24,00



Roof, Scratch(es), LI - Repair and paint (complete)

385,20



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68




Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

414,56



Seat cover R R, Stain, Acceptable

0,00




Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,68



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

440,40



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44

Bumper R, Scratch(es), LI - Repair and paint (complete)		169,44
		
Bumper F, Scratch(es), LI - Repair and paint (complete)		169,44
		
Ignition key, Missing, E - Replace		150,00
No pictures to display		
Door frame R R, Dent(s), It - Spot repair		115,56
		