


FORD S Max: 1HNV595

Vinnumber:	WF0SXXGBWSEM75626	Versionname:	S-MAX Trend Style St/St DPF 115PK
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	100050	Power Kw:	85
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	1224
Maintenance	GEEN MELDING		
Battery functioning	Yes		
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Seats electric F L
GPS storage	Central consol F
GPS storage	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/60/16/99 H LightMetal			
Winter tyres:	Fr.L.	Goodyear: 2 mm	Fr.R.	Goodyear: 2 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			913,64
Bumper R, Scratch(es), E - Replace			483,84



Alloy rim F L, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel bolt cover R R, Missing, E - Replace	10,00



Wing F L, Dent(s), Acceptable	0,00
No pictures to display	
Wing R L, Dent(s), Acceptable	0,00
No pictures to display	
Door R R, Dent(s), Acceptable	0,00
No pictures to display	
Wheel bolt cover F L, Missing, E - Replace	15,00



Bumper F, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Windscreen, Repaired, Acceptable	0,00
No pictures to display	
Door R L, Dent(s), Acceptable	0,00
No pictures to display	
Bumper grille, Scratch(es), Smart repair	110,64



Wheel bolt cover F R, Missing, E - Replace	15,00
--	-------



Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Wheel bolt cover R L, Missing, E - Replace	25,00
--	-------

