



RENAULT CLIO GRANDTOUR: 1NVH616

Vinnumber:	VF17RBF0A55340341	Versionname:	1.5 ENERGY DCI 75 EXPRESSION
First Registrationdate:	4/05/2016	Fiscalpower:	
Expertise Mileage:	128330	Power Kw:	55
Bodytype:		Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3614
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Windows electric F	Luggage cover
Steering wheel multifunctional	Rear parking sensors
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	185/65/15/88 H Steel			
	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
Total cost ex VAT			1042,76
Seat cover F L, Burned, E - Replace			312,00



Wheel cover R L, Scratch(es), E - Replace

24,00



Mirror side blinker L, Crack, Acceptable

0,00

No pictures to display

Door F L, Scratch(es), LI - Repair and paint (complete)

254,68



Centre console, Scratch(es), Smart repair

110,64



Mirror side blinker R, Waterinfiltration, E - Replace

28,80



Seat cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Rocker panel inner R R, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), Acceptable

0,00

No pictures to display

Ignition key, Worn, Acceptable

0,00

No pictures to display

Trunk lid covering R, Scratch(es), Smart repair

110,64



Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Rocker panel inner F L, Dent(s), PDR - Paintless dent repair

52,00



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Ignition key, Missing, E - Replace

150,00



Bumper F, Scratch(es), Acceptable

0,00

No pictures to display