



RENAULT Trafic: 1ESP710

Vinnumber:	VF1FLB10SDY487913	Versionname:	TRAFIC 29 B/F L2H2 Gr.Conf.FAP(EU5)115PK
First Registrationdate:	11/03/2013	Fiscalpower:	
Expertise Mileage:	126468	Power Kw:	84
Bodytype:		Body color	White
Gearbox:	MAN 6 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	LCV21
Number of doors	5		
Number of seats	3		
Number head rests	3		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/65/16/106 T Steel			
Summer tyres:	Fr.L.	Vredestein: 0 mm	Fr.R.	Vredestein: 0 mm
	Re.L.	Michelin: 0 mm	Re.R.	Dunlop: 0 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	-----	------	-----

Total cost ex VAT	3707,13
-------------------	---------

Wing R L, Dent(s), LI - Repair and paint (complete)	231,15
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Bumper corner R L, Scratch(es), Smart repair

110,64



Seat cover F L, Stain, Cleaning

25,00



Spare wheel, Missing, E - Replace

153,60



Wing R R, Dent(s) and scratch(es), Acceptable

0,00

No pictures to display

Door panel F L, Hole, E - Replace

91,50



De-icer nozzle internal R, Broken, E - Replace

153,00



Door moulding Lower R R, Missing, E - Replace

91,50



Ceiling, Hole, E - Replace

406,50



Tyre R L, Not original part, E - Replace

105,00





Windscreen, Stone chip(s), E - Replace

395,40



Door R R, Dent(s) and scratch(es), Le - Replace and paint

746,18



Bumper R, Hole, E - Replace

329,40



Trunk door R R, Dent(s), LI - Repair and paint (complete)

238,00



Interior, Worn, Acceptable

0,00

No pictures to display

Door F R, Dent(s), It - Spot repair

163,56



De-icer nozzle internal L, Broken, E - Replace

153,00



Bumper corner R R, Crack, E - Replace

81,20



Wheel cover F R, Missing, E - Replace

22,50



Wheel cover F L, Missing, E - Replace

22,50



Rear wiper blade, Missing, E - Replace

15,00



Wheel cover R R, Missing, E - Replace

22,50

