



VOLKSWAGEN TOURAN: EG3004

Vinnumber:	WVGZZZ1TZGW537116	Versionname:	2.0 TDI SCR 110KW BMT HIGHLINE
First Registrationdate:	15/01/2016	Fiscalpower:	
Expertise Mileage:	63934	Power Kw:	110
Bodytype:	MPV	Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1129
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Sun Roof electric	
GPS storage	SD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining semi-Alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 V LightMetal				
Summer tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Pirelli: 8 mm	Re.R.	Pirelli: 8 mm

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Total cost ex VAT	2595,30
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Bonnet, Stone chip(s), Acceptable

0,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rear window, Scratch(es), E - Replace

370,00






Door F L, Dent(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)	115,56
---	--------



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)	310,50
---	--------



Wing R R, Scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Rocker panel inner R R, Dent(s), Acceptable	0,00
---	------

No pictures to display

Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------

