









81	
W.	No. 10



Vinnumber:	WBA5L31070G082326	Versionname:	2.0 520D (120KW) TOURING
First Registrationdate:	3/08/2015	Fiscalpower:	
Expertise Mileage:	118001	Power Kw:	120
Bodytype:	Break	Body color	Beige
Gearbox:	Automatic	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1315
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	ок		
Registration Certificate Car (BE)	Yes		

Options

Radio CD
Seats electric F L
Windows electric F
Windows electric R
Central consol F
Cruise Control
Luggage cover
Steering wheel multifunctional
Front parking sensors
Seats F heated
Rear parking sensors
Radio multimedia
Type of Tow bar

Type of headlighting Headlighting Halogen
Type of GPS GPS big screen color
Type of Lining Lining leather
Type of climate control Autom climate control

Head-up Display Sport seats

	Type of Tow bar	No Tow bar
Halogen		

Limited Technical Inspection

Airco functioning	ок	Battery functioning	Yes
Tires wear profile	ок	Power steering	Yes
Idle position	ок	Sound engine	ок
Engine startingtime	ок	Clutch test	ок
Exhaust gass	ок	Wiper fluid level	ок
Handbrake	ок	Transmission	ок
		Lighting	ок
		Winerblades	OK

Degree of wear

	225/55/17	/97 Y LightMetal		VICTOR CONTRACTOR OF THE CONTR
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance	equipment
------------	-----------

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1422,58
Rocker panel inner R L, Dent(s), LI - Repair and paint (complete)		115,56	





Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00









Wing R L, Scratch(es), LI - Repair and paint (complete)

369,84





Door R L, Scratch(es), LI - Repair and paint (complete)

382,02






Bonnet, Bad repair, Acceptable

0,00











Wing R R,	Scratch(es), Acceptable
No pictures	to display
Protection	plate M, Tear, E - Replace

74,00





Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

254,16















Door panel F L, Worn, E - Replace 132,00



