



VOLKSWAGEN Crafter 35 MWB hoog dak: 1BJR371

Vinnumber:	WV1ZZZ2EZB6023448	Versionname:	CRAFTER 35 B/F MWB HR 109pk
First Registrationdate:	16/06/2011	Fiscalpower:	
Expertise Mileage:	209044	Power Kw:	80
Bodytype:	Transporter	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	LCV10
Number of doors	5		
Number of seats	3		
Number head rests	3		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		

Options

Radio CD		Central consol F	
Windows electric F		Rear parking sensors	
Type of headlighting	Headlighting Halogen	Type of Tow bar	Tow bar fixed
Type of GPS	No GPS		
Type of Lining	Lining artificial leather		
Type of climate control	No climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	235/65/16/115 R Steel			
	Fr.L.	Michelin: 9 mm	Fr.R.	Michelin: 9 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Spare wheel	Yes
-------------	------------

Total cost ex VAT	2097,94
-------------------	----------------

Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)	238,76
---	---------------



Bumper F, Scratch(es), Smart repair

110,64



Rearview mirror housing R, Scratch(es), Smart repair

110,64



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76




Spare wheel compartment lining R R, Dent(s), Smart repair

110,64



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Seat cover F L, Damaged, E - Replace

300,00



Spare wheel compartment lining R L, Dent(s), Smart repair

110,64



Door R R, Dent(s), PDR - Paintless dent repair

82,80



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Sidewall panel RL, Broken, E - Replace

74,00



Trunk door panel L, Broken, E - Replace

20,00

