



PEUGEOT PARTNER: 1GKC920

Vinnumber:	VF37E9HF0EJ537133	Versionname:	
First Registrationdate:	28/02/2014	Fiscalpower:	
Expertise Mileage:	161743	Power Kw:	65
Bodytype:	Transporter	Body color	White
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1329
Number of doors	5		
Number of seats	2		
Number head rests	2		
Rims summer	Steel		
Category	Light Commercial Vehicle		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Type of headlighting	Headlighting Halogen	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Winter tyres:	195/65/15/91 H Steel			
	Fr.L.	Uniroyal: 4 mm	Fr.R.	Uniroyal: 4 mm
	Re.L.	Uniroyal: 6 mm	Re.R.	Uniroyal: 6 mm

Assistance equipment

Spare wheel	Yes
-------------	-----

Total cost ex VAT	1371,65
Bumper R, Dent(s), Smart repair	110,64



Rearview mirror housing L, Crack, LI - Repair and paint (complete)

115,56



Door moulding Lower R R, Scratch(es), E - Replace

91,50



Trunk door R R, Dent(s) and scratch(es), It - Spot repair

115,56



Maintenance book, Missing, E - Replace

0,00

No pictures to display

Rearlight L, Broken, E - Replace

91,50



Wheel cover F R, Deformed / Strained, E - Replace

22,50




Trunk door panel L, Hole, E - Replace

44,00



Wheel cover F L, Deformed / Strained, E - Replace

22,50




Instruction book, Missing, E - Replace

0,00

No pictures to display

Roof, Dent(s) and scratch(es), LI - Repair and paint (complete)

361,13



Door moulding Lower F R, Scratch(es), E - Replace

91,50



Wheel cover R R, Deformed / Strained, E - Replace

22,50



Interior, Dirty, Cleaning

0,00

No pictures to display

Trunk door panel R, Hole, E - Replace

44,00



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76

