



PEUGEOT 5008: 1LEJ513

Vinnumber:	VF30EBHZTFS219342	Versionname:	1.6 BLUEHDI 5&S 88KW AUTO ALLURE
First Registrationdate:	4/09/2015	Fiscalpower:	
Expertise Mileage:	113018	Power Kw:	88
Bodytype:	MPV	Body color:	Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1215
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Panoramic roof
Windows electric F	Central consol F
Windows electric R	Luggage cover
Cruise Control	Front parking sensors
Seats F heated	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	215/50/17/95 W LightMetal			
	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Total cost ex VAT	1333,44
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00





Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Luggage space cover, Missing, E - Replace

240,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Door F L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00





Internal Boot Lining L, Scratch(es), Smart repair

110,64



Tailgate, Dent(s), PDR - Paintless dent repair

82,80



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Sill outer R, Dent(s), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00

No pictures to display