



TOYOTA AURIS TOURING SPORTS: 1TBQ159

Vinnumber:	SB1Z53JEX0E346044	Versionname:	1.8 VVT-i Hybrid CVT Business Plus
First Registrationdate:	15/09/2017	Fiscalpower:	
Expertise Mileage:	24053	Power Kw:	73
Bodytype:		Body color	Blue
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Hybrid Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	2822
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/95 V LightMetal			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	401,80
Door R L, Dent(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00



Door F R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper F, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00



Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Tailgate, Scratch(es), Acceptable	0,00
No pictures to display	
Wing R L, Scratch(es), Acceptable	0,00
No pictures to display	