



VOLKSWAGEN Touran: 1GCV364

Vinnumber:	WVGZZZ1TZEW050021	Versionname:	TOURAN Highline BMT Start/Stop 105PK
First Registrationdate:	3/01/2014	Fiscalpower:	
Expertise Mileage:	157264	Power Kw:	77
Bodytype:		Body color	Black
Gearbox:	MAN 6 VIT	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2322
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	No Tow bar
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		


Total cost ex VAT	1596,98
Bumper R, Scratch(es), LI - Repair and paint (complete)	211,80



Alloy rim F L, Scratch(es), Acceptable	0,00
No pictures to display	
Alloy rim F R, Scratch(es), Acceptable	0,00
No pictures to display	
Door R R, Scratch(es), Acceptable	0,00
No pictures to display	
Tailgate, Scratch(es), LI - Repair and paint (complete)	301,68



Protection plate M, Deformed / Strained, E - Replace	128,00
--	--------



Door R L, Scratch(es), Acceptable	0,00
No pictures to display	
Rear window, Scratch(es), E - Replace	370,00



Rearview mirror housing R, Broken, E - Replace	104,00
--	--------



Roof, Chemical polution, LI - Repair and paint (complete)	481,50
---	--------

